

مقدمة

- شكرا لاستخدامك منتجنا عاكس المضخات التي تعمل بالطاقة الشمسية (SG600 series solar pump inverter)
- هذا الكتالوج يشرح لك كيف تستخدم الجهاز بطريقه مثاليه .اقرأ الكتالوج بحرص وأكملة للنهائة ،وافهم احتياطات الأمن والتحذير قبل (التركيب -ربط الاسلاك- التشغيل -الصيانة -والفحص والي آخر ذلك) .
- الكتالوج يتضمن بداخله كل المعاملات التي تحتاج إلي ضبط ومميزات البرنامج المحددة لهذا الانفرتر SG600
- المميزات الرئيسية لهذا الانفرتر :-
 1. خاصية التشغيل والفصل الآلي (اضبط 1=PO-02) .
 2. أقصى دخل DC يصل الي 1000 Vdc فولت)
اختياري مع الموديل SG600-5T (.
 3. يقدر يشغل مضخة أحادية الطور (فازة واحدة) حتي 220 فولت .
 4. تشغيل مستقر و تقلبات ترددية قليلة .
 5. حماية شاملة وعاكس لا يحترق .
 6. سهل التركيب وتوصيل الأسلاك والتشغيل .
 7. يوجد GPRS للمراقبة عن بعد ووظيفة التحكم .

المحتوي

الفصل الأول	قبل الاستخدام
الفصل الثاني	مقدمه لنظام المضخات الشمسية
	2.1 نظرة عامة علي نظام مضخات الطاقة الشمسيه
	2.2 مميزات نظام مضخات الطاقة الشمسيه
الفصل الثالث	نظرة عامة علي عاكس مضخات الطاقة الشمسية
	3.1 مميزات المنتج
	3.2 نظرية تشغيل عاكس المضخات الشمسية
	3.3 عاكس المضخات الشمسية المتوافق مع نموذج المصدر المزدوج
	3.4 وصف عاكس المضخات الشمسية (SG600)
	3.5 الموديلات (نماذج) والمواصفات
	3.6 المواصفات التقنية لعاكس المضخات الشمسية (SG600)
	3.7 أبعاد العاكس (SG600)
الفصل الرابع	وصف لوحة التحكم للتشغيل
الفصل الخامس	تركيب العاكس (SG600)
الفصل السادس	التشغيل والمراقبة
الفصل السابع	قائمة بسيطة للمعاملات (parameters)
الفصل الثامن	وصف معاملات التحكم للمضخة الشمسية
الفصل التاسع	اكتشاف الاخطاء وإصلاحها
الفصل العاشر	روتين التفيتيش والصيانة
ملحق 1	عاكس المضخات الشمسية (SG600) لتشغيل مضخة أحادية
الطور 220 فولت .	
ملحق 2	تعليمات إضافية لعاكس المضخات الشمسية لمضخات PMSM
(محرك تزامني ذو مغناطيس دائم) .	
ملحق 3	بروتوكول الاتصالات
ملحق 4	اختيار الاجهزة الطرفية من SG600

الفصل الأول قبل الاستخدام

اقرأ واتبع جميع الإرشادات !!

- عند تركيب واستخدام هذا الجهاز ،احتياطات الأمان الأساسية يجب دائما أن تتبع ،تتضمن التالي :-

تحذير لتقليل خطر الإصابة ،لا تسمح للأطفال باستخدام هذا المنتج ما لم يتم الإشراف عليها عن قرب في جميع الاوقات .

تحذير لتقليل خطر الصدمات الكهربائية ،استبدال الحبل التالف في الحال .

تحذير يجب التأكد من إجراء جميع اتصالات التأريض بشكل صحيح وأن المقاومة تفي بالمتطلبات أو المتطلبات المحلية .

- احتياطات الأمان

1.1 تحذيرات عامة

الكتالوج يحتوي علي إرشادات أساسية التي يجب مراعاتها أثناء التركيب والتشغيل والصيانة .
الكتالوج يجب أن يقرأ بحرص قبل التركيب والبدأ من قبل الشخص المسئول عن التثبيت .
الكتالوج يجب أن يقرأ من قبل التقنيين الاخرين والمشغلين ولا بد أن يكون متاح في موقع التثبيت في جميع الأوقات .تأهيل الموظفين وتدريب جميع الموظفين للتشغيل والصيانة والتفتيش ويجب ان يكون التثبيت مؤهلا تماما لأداء هذا النوع من العمل .
المسؤولية والكفاءة والاشراف علي هؤلاء الموظفين يجب أن تنظم من خلال المستخدم .
إذا كان الموظفون المتاحون يفتقرون الي المؤهلات اللازمة ،يجب تدريبهم وتوجيههم وفقا لذلك .
إذا لزم الأمر ، قد يطلب المشغل من الشركة المصنعه توفير هذا التدريب .
المشغل او المستخدم يجب أن يتأكد تماما من أن الموظفين يفهمون مجتوي الكتالوج جيدا .
أخطار تجاهل رموز الأمان – تجاهل رموز الأمان ممكن يسبب خطر للانسان والبيئه وللجهاز ذات نفسه .عدم الالتزام قد يبطل أي ضمان .

- عدم الإلتزام بإرشادات الأمان والرموز ممكن يسبب التالي :
فشل او انهيار وظائف مهمة للمعدة أو المحطه –فشل الطرق المحددة للصيانة
والتصليح –تعرض الاشخاص للخطر من خلال التأثيرات الكهربائية والميكانيكية
والكيميائية-خطر للبيئة بسبب تسرب مواد خطرة –خطر تلف المعدة او الجهاز
والمباني .

• عملية موجهة نحو السلامة :-

ارشادات السلامة الموجودة في الكتالوج ،يجب مراعاة اللوائح الوطنية الحالية للوقاية من الحوادث وكذلك الارشادات الداخلية وأنظمة السلامة للمشغل .ارشادات سلامة عامة للمستخدم-لو أجزاء باردة أو حارة تشير إلي خطر اذن يجب ان تُحمي من خلال المستخدم ضد الاتصال بالأشخاص .الأغطية الوقائية للأجزاء المتحركة يجب ألا تزال أثناء تشغيل الجهاز .يجب التخلص من تسربات الضخ الخطرة بطريقة تتم إزالة اي خطر علي الموظفين والبيئة .جميع الحكومات والمنظمات المحلية يجب ان تلاحظ في جميع الأوقات .أي خطر للأشخاص من الطاقة الكهربائية يجب استبعاده باستخدام ممارسات التثبييت الجيدة والعمل وفقا للوائح المحلية .ارشادات السلامة للصيانة والتفتيش ومجموعة العمل ،إنها مسئولية المستخدم للتأكد من أن جميع الصيانات والتفتيش ومجموعة العمل يتم تنفيذها حصريا من قبل خبراء مؤهلين ومؤهلين علي دراية كافية بما يكفي من خلال الإطلاع الدقيق علي تعليمات التشغيل .منظمات منع الحوادث يجب أن تشرف .أي شغل علي المعدة يجب أن يتم عندما تكون المعدة لا تعمل ومعزولة تماما عن الكهرباء .الطريقة التسلسلية لإغلاق المعدة او الجهاز وُصفت في هذا الكتالوج ويجب التقيد بها بصرامة .يجب تطهير المضخات أو وحدت المضخات التي تتعامل مع المواد الخطرة .عند الانتهاء من العمل ،يجب استعادة وتفعيل جميع معدات السلامة والحماية .قبل اعادة تشغيل المعدة ،كل النقاط في فصل **(بدء التشغيل الأولي)** يجب التقيد بها .

لا يجوز إجراء تغييرات غير مصرح بها وتصنيع قطع غيار –أي تحويل او تغييرات في المعدات يتم فقط بعد استشارة الشركة المصنعة .تضمن قطع الغيار والملحقات الأصلية المعتمدة من الشركة المصنعة السلامة التشغيلية .استخدام قطع غيار غير معتمدة قد يبطل أي مسئولية للشركة المصنعة .التشغيل غير مصرح به –يتم ضمان السلامة التشغيلية للمعدات فقط إذا تم استخدام الجهاز وفقا للإرشادات في هذا الدليل .لا يجوز تجاوز الحدود المنصوص عليها في الداتا شيت تحت أي ظرف من الظروف .التبديل والتخزين في بيئة عالية الرطوبة وحراره متقلبة يجب تجنبه تماما .الرطوبة والتكثيف ممكن يتلف الملفات والأجزاء المعدنية .عدم الالتزام سوف يبطل أي ضمان .

1.2 نفتيش الشراء

⚠ تحذير ينبغي فحص الجهاز قبل التركيب ،لا تركبه إذا وجدت به تلف أو جزء مفقود، التركيب يعطل او غير كامل ممكن يسبب حوادث .

⚠ تحذير المحرك الغاطس محرك متناوب مغمور بالماء ،راقب التعليمات المرفقة مع المحرك وفقا لمياهه .هذه التعليمات قد تجدها في دليل المحرك أو علي جسمه .تجاهل هذه التعليمات يقصر من عمر المحرك ويتلفه .

1.3 التركيب

تحذير لتبريد فعال ،الجهاز يجب أن يركب رأسيا مع ترك فراغ لا يقل عن 10 سم أعلي وأسفل الغلاف .

تحذير عند تركيب الجهاز في مكان داخلي يجب توفير التهوية الكافية وعدم تثبيته في مكان معرض للشمس مباشرة .

تحذير لا تدع رقائق الحفر تقع داخل مروحة الجهاز لأنها ستؤثر علي توزيع الحرارة .

1.4 التوصيلات

تحذير التوصيل يجب أن يتم بفريق مؤهل جدا ،الفريق الغير مؤهل قد يسبب صدمات كهربيه وحريق وموت .

تحذير تأكد مرتين من فصل المصدر قبل توصيل الجهاز ،غير ذلك سيسبب صعق كهربي وحريق .

تحذير يجب أن تكون المحطة مؤرضة كما ينبغي ،غير كذا لمس هيكل الجهاز قد يسبب صدمة كهربية .

تحذير اختيار ألواح الطاقة الشمسيه والمحرك والجهاز يجب أن يكون كافي حتي لا يدمر المعدة .

تحذير تأريض المعدة شئ إلزامي ،لا تشغل المضخة إذا كان سلك الأرضي غير متصل لنظام التأريض .إهمال هذا الإرشاد قد يؤدي لصدمة كهربية .

1.5 التشغيل

تحذير الجهاز يجب أن يعمل بعد التوكد من صحة التوصيلات حتي لا تسبب اتلاف .

تحذير لا تعدل في التوصيلات والجهاز شغال أو تلمس أي شئ ممكن يسبب صدمة كهربيه .

تحذير ضبط معاملات التحكم الجزئي كما موضح بالدليل قبل أول تشغيل .لا تغير معاملات التحكم بشكل عشوائي وإلا سيسبب تلف للمعدة .

تحذير أثناء التشغيل تسخن بعض الأشياء لا تلمسها حتي تبرد حتي لا تحترق .

تحذير الارتفاعات الأكثر من 1000متر فوق سطح البحر ،تيار الخرج يجب أن يقل 10 % لكل 1500متر زيادة في الارتفاع .

تحذير لا تشغل المضخة إذا لم تكن مغمورة تماما في الماء ،عند تثبيت المضخة ،يمكن تحديد اتجاه تشغيل الصحيح عن طريق قياس معدل التدفق (التصريف) .

الفصل الثاني مقدمة للمضخات الشمسية

2.1 نظرة عامة للمضخات الشمسية :-

أنظمة المضخات شمسية ممكن تُطبق علي كل أشكال الاستخدام اليومي ،ضخ الماء للشرب وللقري البعيدة وللمزارع الغير متصلة بشبكة الماء .في الزراعة يستخدم لسقي الماشية وري الزرع وري الغاباتوفي الصناعة معالجة المياه .


في السنوات الأخيرة بعد تعزيز استخدام مصادر الطاقة المتجدده ،أنظمة المضخات الشمسية مُستخدمة بكثرة في الهندسة البلدية وساحات وسط المدينة والحدائق والمواقع السياحية والمنتجات والقري السياحية وأنظمة النافورة في المناطق السكنية .

النظام مكون من مولد شمسي (ألواح شمسية) و طلمبة (مضخة)وعاكس للمضخات الشمسية،معتمدة علي فلسفة التصميم وهي أن أكث كفاءة تخزين الماء علي تخزين الكهرباء ،لا يوجد في هذا النظام أجهزة تخزين مثل البطاريات .

المولد الشمسي ،الألواح الشمسية تتصل علي التوالي او التوازي ،تمتص الاشعاع الشمسي وتحوله لطاقة كهربية ،توفر الطاقة للنظام كله .العاكس يحول التيار المستمر من الألواح إلي متردد (متناوب) لتشغيل المضخة ويعدل التردد الذي يتغير وفقا للاشعاع ليعطي اكبر قدره (mmpt).

المضخة تُحرك ب موتور أحادي أو ثلاثي الطور تستطيع ضخ الماء من الآبار أو الأنهار وضخها لخزانات الماء أو مباشرة لنظام الري أو النافورة وغير ذلك .

شكل أنظمة المضخات الشمسية (ألواح شمسية وعاكس ومضخة)




2.2 مميزات أنظمة المضخات الشمسية

الحفاظ على تكلفة الطاقة وزيادة الإنتاجية. تضمن عواكس المضخات الشمسية مصدر طاقة موثوق طوال اليوم من خلال التوافق بين الشبكة المتصله والمنفصلة عن الشبكة .

الحفاظ على البيئة تسخير الطاقة الشمسية يضمن ضخ صديق للبيئة بدون انبعاثات لغاز ثاني اكسيد الكربون . سهل التركيب والتشغيل ومعاملات تكوينية قليلة . وأي شخص لم يستخدم العواكس قبل ذلك يستطيع التعامل معها جيداً .

تقليل تكلفة الصيانة العواكس مجهزة بخيارات المراقبة عن بعد وتقليل زيارات الصيانه للموقع .

تقليل مخاطر التشغيل جزأ لا يتجزأ من مميزات المضخه المحددة حماية ضد التشغيل الجاف ، حماية ضد أقل دخل للطاقة، حماية ضد زيادة التيار وحماية وقت تردد التشغيل .



الفصل الثالث نظرة عامة علي عواكس المضخات الشمسية

عواكس الفايوتون هي اجهزة ذات جهد متناوب منخفض من 3. كيلو وات الي 100 كيلو وات أعلي تصنيف ،مصممة للعمل مع الطاقة الصادرة من الألواح الشمسية.

العواكس مجهزة لتعمل في نظام ثنائي تبادلي تعمل علي الشبكة في غياب الطاقة الشمسية .يعمل هذا العاكس مع أحدث التقنيات (mppt) **تتبع أقصى نقطة للطاقة** ،للحصول علي أكبر قدرة من المنظومة الشمسية في أي لحظة.العاكس مصمم للتوافق مع متطلبات مصنعي المضخة وكذلك مصنعي المعدات الأصلية .

3.1 مميزات المنتج :-


- ✚ تتبع أقصى نقطة للطاقة مع الاستجابة السريعة والتشغيل المستقر كفاءته أكبر من 99%.
- ✚ مناسب لمضخات ثلاثي الطور المتناوب ومضخات PMSM المحركات التزامنية ذو مغناطيس دائم ذات الكفاءة العالية .
- ✚ جهد التشغيل للألواح الشمسية ممكن تضبط يدويا أو آليا ب mppt .
- ✚ متوافق مع دخل ثنائي للطاقة ،شبكة الكهرباء العمومية أو من منظومة الشمسية تيار مستمر .
- ✚ حماية التشغيل الجاف .
- ✚ حماية ضد زيادة التيار .
- ✚ حماية ضد أقل دخل للقدرة .
- ✚ حماية وقت تردد التشغيل .
- ✚ منحنى أداء PQ (معدل التصريف والقدرة)يمكن من معرفة معدل التصريف للمضخة.
- ✚ التحكم الرقمي للتشغيل الآلي كاملا وتخزين البيانات ووظائف الحماية.
- ✚ نموذج الطاقة الذكي IPM للدائرة الرئيسية لافضل أداء وتوفير الحماية.
- ✚ لوحة عرض التشغيل ودعم التحكم عن بعد .
- ✚ مستشعر التحكم بانخفاض مستوى الماء ووظائف التحكم بمستويات الماء .
- ✚ حماية البرق القوي.
- ✚ درجة التشغيل من سالب 10 الي موجب 50 درجة سليزيوس.

3.2 نظرية تشغيل عواكس المضخات الشمسية :-

عاكس المضخات الشمسية يستخدم برنامج التحكم mppt لتتبع اقصى نقطة تتبع لتوفير أعلي كفاءة للأنظمة الشمسية .خرج الخلايا الشمسية يتناسب مع مساحته وشدته،جهد وصلة p-n (شبه فكرة الدايد) يتراوح من 6. الي 7. فولت . وعند ثبات الجهد القدرة بتتناسب مع المساحة وشددة الاشعاع.الجهد والتيار الذين ينتجوا أعلي قدرة معروفين ب نقطة أقصى قدرة .

متحكم ال mppt نقطة تتبع أقصى قدرة يتبع خطط مختلفة لإنتاج أقصى قدرة من الخلايا الشمسية. وهذا يتحقق بضبط جهد التشغيل للخلايا والتيار لحين للوصول لأفضل قدرة.


عندما يكون جهد الخرج صفر، الخلية الشمسية تعمل تيار قصر. في حالة عدم اتصال الخلايا بحمل، جهد الخرج هيساوي جهد الداية المفتوحة. نقطة أقصى قدرة بتكون علي نقطة في المنحني ناتجة من اقصى جهد وتيار مناسب لاعلي قدرة .



منحني التيار والجهد غير ثابت بيتغير بتغير الحرارة وشدة الإشعاع أثناء اليوم. في درجة حرارة ثابتة، التيار يتغير خطيا مع شدة الإشعاع والجهد يتغير بشكل لوغاريتمي مع شدة الإشعاع. وبما إن التغير في الجهد صغير بالنسبة للتغير في شدة الإشعاع أقصى قدرة تتناسب مع شدة الإشعاع .

3.3 عاكس المضخات الشمسية فاي تون متوافق مع المصدر الثنائي (افيلشبكة/منظومة شمسية):-

يستخدم مفتاح مغير أربع أقطاب (مفتاح قلاب) للتغيير بين المصدرين الشبكة AC والخلايا الشمسية DC. في وقت محدد مصدر واحد فقط يتصل بالعاكس .



Power, current and voltage specification (2S /2T 220VAC voltage, and 4T/380VAC voltage

القدرة Rated power/kw	تيار أحادي الطور 2S 220V range	تلاثي الطور 4T 380V range
	Rated current /A	Rated current /A
0.4	2.3	None
0.7	3.8	2.3
1.5	5.1	3.8
2.2	9	5.1
3.7	13	10
5.5	25	13
7.5	32	17
11	45	25
15	60	32
18.5	75	37
22	91	45
30	110	60
37	152	75
45	176	91

3.5 النماذج والمواصفات :-

لاحظ إن الرقم الذي قبل P هو ال بيكون الكسر علي يمين العلامة العشرية و ال G وحدها الرقم بيكون رقم صحيح .

**Solar pump inverter specification when PE-00=1&2	
Recommended MPPT voltage range	Vmp 131 to 350 VDC for 1S model (80V to 350VDC input, 3PH 110 to 220VAC output) Vmp 260 to 355VDC for 2S/ 2T model (150V to 350VDC input, 3PH 220 to 240VAC output) Vmp 486 to 650 VDC for 4T model (250V to 800VDC input, 3PH 380 to 460VAC output)
Recommended input Voc and Vmpp voltage	Voc 180(VDC), Vmpp 155(VDC) for 1S model or 110V AC pumps Voc 380(VDC), Vmpp 310(VDC) for 2S model or 220V AC pumps Voc 650(VDC), Vmpp 520(VDC) for 4T model or 380V AC pumps
Motor type	Control for permanent magnet synchronous motor(PMSM) and asynchronous motor pumps.
Rated output voltage	1/3-Phase,110V/160V/220V. 3-phase, 220V/380V/480V
Output frequency range	0~maximum frequency 320Hz.
MPPT efficiency	99.7%,
Ambient temperature range	G-type for submersible pumps,150% rated current for 60s, 180% rated current for 2s. P type for general pumps,120% rated current for 60s,150% rated current for 2s.
Solar pump control special performance	MPPT (maximum power point tracking), CVT (constant voltage tracking), auto/manual operation, dry run protection, low stop frequency protection, minimum power input, motor maximum current protection, flow calculating, energy generated calculating and water tank level detected

Recommended MPPT voltage range الجهد الموصى به لشاحن الانفرتر الداخلي .

Recommended input Voc and Vmpp voltage الجهد الموصى به للدائرة المفتوحة وجهد التشغيل .

Motor type نوع الموتور.

Rated output voltage جهد الخرج الاسمي.

Output frequency range نطاق تردد الخرج.

Ambient temperature range نطاق درجة الحرارة .

Solar pump control اداء التحكم في المضخات (تتبع اقصى نقطة للقدرة mppt -تتبع الجهد الثابت-تشغيل يدوي وآلي -حماية التشغيل الجاف-حماية انخفاض التردد-انخفاض قدرة الدخل-حماية زيادة التيار-حساب التصريف-حساب القدرة المنتجة ومستوي الماء)

special performance

Protection function	Phase loss protection, phase short circuit protection, ground to phase circuit protection, input and output short circuit protection. Stall protection, lightning protection
Protection degree	IP20, Air force cooling
Running mode	MPPT or CVT
Altitude	Below 1000m; above 1000m, derate 1% for every additional 100m
Enhanced version of AC drive	CE, Design based on vector control motor AC drive, more specification please refer to S100 vector control drive operation manual
**Technical specification of variable frequency inverter when PE00=0 (solar pump disable)	
voltage, frequency	1 phase 220V, 3 phase, 220V, 380V, 660V, 0-50/60Hz
Control mode	0: VF control ; 1: Open loop vector control mode 2: Close loop vector control mode
Maximum frequency	0-320Hz in vector control mode, 0~3200Hz in VF control mode
Multiple-functions	PID Control, Carrier Frequency Adjustable, Current Limiter, Speed Search, Momentary Power Loss Restart, 16 Step Speed (Max), 3-Wire connection, Slip Compensation, Frequency Jump, DC braking, Upper/Lower Frequency, Torque control, Compatible for PMSM and IM, built in RS485, counting, fault information checking, fully fault protection function, frequency combination reference.



Protection function (حماية فقد فـازة (طور) –حماية ضد قصر الفـازة او الطور –حماية ضد قصر أرضي مع خط –حماية دخل وخرج القصر-حماية العطل – حماية البرق)
Protection degree (حماية درجة الحماية (هواء مدوع بمروحة). Altitude (الارتفاع).

3.7 أبعاد العاكس

3.7.1 الانفرتر الحجم الصغير :-



3.7.2 العاكس العام



الفصل الرابع وصف لوحة تحكم التشغيل

4.1 وصف مفاتيح

وصف الوظيفة	الاسم	رمز المفاتيح
قائمة الادخال	مفتاح القائمة	PRG
تدخل للقائمة خطوة بخطوة أو تأكيد قيمة	مفتاح التأكيد	enter
	التحرك لاعلي في القائمة	↑
	التحرك لأسفل في القائمة	↓
	التحرك لليسار في القائمة	←
	التحرك لليمين في القائمة	→
باختيار وضع المراقبة يمكنه عرض المعاملات بتسلسل جهد-تردد ...	زر التشغيل	Run تشغيل
يستخدم لتشغيل الموتور في لوحة التحكم		
		MF مفتاح متعدد الوظائف
يستخدم لايقاف الموتور P0-02		Stop ايقاف reset اعادة ضبط

4.2 الرموز المستخدمة

Symbol	Indicator description
Hz	Unit of frequency (Hz) تردد
A	Unit of current (Amp) تيار
V	Unit of voltage (V) جهد
RUN	Forward run indicator
DIR	Inverter runs in terminal control mode, when P0-02=1 setting
LOCAL	Inverter runs in keyboard control mode, when P0-02=0 setting
TRIP	Fault indicator, inverter will be trip when any alarm happens

Trip موضع الاخطاء هيفصل الانفرت لو ظه اي خطأ.

4.3 مساحة العرض الرقمي

خمس عروض رقمية ممكن تتم عرض اشارة التردد وخرج التردد ووانواع بيانات الرصد وكود تنبيه الخطأ.

4.4 وظيفة رمز التشغيل

1-رموز وظايف المعاملات. (المستوي الاول)

2-اسم معاملات الوظائف. (المستوي الثاني)

3-ضبط القيمة للرمز (المستوي الثالث)

في المستوي الثالث ممكن تضغط enter او PRG لكي تعود للمستوي الثاني ولكن هناك فرق


1. لو ضغطت enter كذا المعاملات ال عدلتها هتتحفظ في ذاكرة العاكس

2- لو ضغطت PRG لن يتم تخزين التعديلات .

مثال علي تشغيل لوحة المفاتيح

1-تعديل مصدر الاوامر للتحكم في النهايات او المحطة ،المضخه هتبدأ لم مفتاح ال DLI و GND يشتغل .لو مفتاح DLI, GND في وضع التشغيل العاكس هيشغل آليا في الصباح ويقفل مع المساء .

2-تعديل القدرة الاسمية للموتور في P1-01 ،لو القدرة الاسمية للعاكس اكبر بكثير من القدرة الاسمية للموتور ،من فضلك اضبط P1-01 للقدرة الاسمية علي لوحة بيانات الموتور لحماية افضل .



4.5-رصد معاملات التحقيق

في طريقتين للتحقق من معاملات الرصد او المراقبة
اضغط (shift) للتحقق من حالة تشغيل معاملات العاكس مثل خرج التردد وخرج التيار وخرج الجهد والجهد المستمر
المستخدم ممكن يروح لمجموعة (U) للتحقق من المعاملات النسبية .
مثال :اضغط PRG للعودة الي شاشة عرض المراقبة للعثور علي مجموعة U ،المستخدم يقدر يحصل علي تردد التشغيل من U0.00 والجهد المستمر من U0.02 .

4.6-اكتشاف الخطأ

العاكس هيعرض معلومات نسبية عن الخطأ لو اي تنبيه ظهر .
المستخدم ممكن يعمل اعادة تعيين من خلال reset او stop أو أطراف خارجية (p4-02=9) عند اعادة تعيين الخطأ
العاكس هيكون في وضع الاستعداد .
في حالة عدم عمل reset للعاكس هيفضل في وضع الحماية ولن يعمل .

الفصل الخامس تركيب عاكس المضخات الشمسية فايتون 381

5.1 عن هذا الفصل :-

هذا الفصل يتضمن معلومات أساسية عن التثبيت الكهربائي والميكانيكي لعاكس المضخات الشمسية .
لإرشادات عامة عن تثبيت وصيانة العاكس (S100 frequency inverter)، من فضلك أشر لدليل S100 .
إرشادات الأمان

تحذير كل التثبيتات الكهربائية والصيانة التي تتم علي العاكس يجب أن تُنفذ بفنيين مؤهلين فقط .

- لا تعمل علي الانفترتر أو دائرة فرملة الكبح braking chooper circuit أو كابلات الموتور عندما تكون الطاقة متصله بالعاكس .
- بعد فصل الطاقة عن العاكس انتظر خمس دقائق حتي مكثفات الدائره المتوسطة تفرغ ويمكنك قياس ذلك للتأكد من عدم وجود جهد.
- مواثير دائمة المغناطيسية الدوارة تنتج فولتية خطيرة، يجب التأكد من غلق الموتور ميكانيكا قبل توصيله للعاكس وقبل عمل أي شغل علي نظام العاكس المتصل بالموتور.

5.2-التثبيت الميكانيكي


تثبيت وربط العاكس علي الحائط بمسامير باستخدام أربع فتحات تثبيت.

متطلبات البيئة للتثبيت:-


- حرارة الجو- درجة حرارة البيئة المحيطة لها تأثير كبير علي عمر التشغيل للعاكس .لاتسمح لدرجة الحرارة أن تزيد عن درجة الحرارة المسموحة (-10 الي 50 درجة سليزيوس).
- توزيع الحرارة-تثبيت العاكس يجب أن يكون علي سطح غير قابل للاحتراق ،والتأكد من أن الفراغ حول العاكس كافي لتوزيع الحرارة ،ثبت العاكس رأسيا باستخدام مسامير التثبيت .
- الاهتزاز-يجب أن يكون أقل من G.6 وبعيد عن ماكينة التخريم وما شابه ذلك.
- خالية من أشعة الشمس المباشرة والرطوبة العالية والتكثيف.
- خالية من الصدا والتفجير وغازات القابلة للانفجار.
- خالية من الزيوت الملوثة والأتربة والمساحيق المعدنية.

5.3-الربط (الاسلاك)والتثبيت :-


5.3.1 مخطط لتوصيلات دخل أحادي الطور 220 فولت



5.3.2- مخطط توصيلات ثلاثي الطور 380 فولت لعاكس قدرته أقل من 30كيلوات



5.3.3-مخطط توصيلات ثلاثي الطور لعاكس اكبر من 30 كيلو وات :-



ملاحظة R و T هم نفسهم (L & N) للتوصيل طرفي المنظومة الشمسية والقطبيه هنا مش هتفرق

لكن عند توصيل علي P+ و N- القطبية مهمة جدا ، غير كذا الانفرتر هيدمر.

- لا تستخدم كابلات غير متشابهه للموتور.
- أدخل كل من كابل الموتور وكابل الطاقة وكابل التحكم بشكل منفصل .
- خليك متأكد إن القيمة العظمي لطول الكابل لم تتجاوزها .لمعلومات تفصيليه شوف الدليل .
- لاحظ القطبيه جيدا عند التوصيل ل- p+/N- .

5.4-وصف أطراف الدائرة الرئيسية:-

رمز الاطراف	وصف الوظيفة
L,N	أطراف الدخول لطاقة الألواح (تيار مستمر) أو دخل متناوب أحادي الطور.
R,S,T	R,T لدخول الألواح الشمسية < R,S,T للدخول ثلاثي الطور متردد
U,V,W	خرج المضخة ثلاثية الطور
P,N	لطرفي الألواح الشمسية ومهم جدا معرفة القطبية للاسلاك والتوصيل الصحيح
P,PB	لطرفي مقاومة الكبح

P1,P	أطراف التوصيل لصدمة ال DC
رمز الارضي	أطراف التأريض

5.5- إجراء التوصيل: -

- 1-تجريد كابل إدخال الطاقة . أرض الدرع العاري من العزل للكابل 360 درجة تحت مشبك التأريض. اربط موصل التأريض لكليل الدخل تحت مسامير مشبك التأريض. وصل كابلات الطاقة من المنظومة الشمسية ل R,T .
- 2-تجريد كابل الموتور . أرض الدرع العاري من العزل للكابل 360 درجة تحت مشبك التأريض. تحريف الدرع لتشكيل جديلة قصيرة قدر الإمكان وتثبيتها تحت مسمار مشبك التأريض. وصل موصلات الطاقة الثلاثة لكليل بنهايات التوصيل U,V,W .
- 3-تأمين الكبلات خارج المحركات الميكانيكية.

5.6-أطراف دائرة التحكم

5.6.1-مخطط أطراف دائرة التحكم:-

485A+10V	AI1	AI2	DI1	DI2	DI3	DI4	DI5	T1/A	T1/B	T1/C	
485B	GND	AO1	AO2	GND	24V	COM	DO1	FM	T2/A	T2/B	T2/C

5.6.2-وصف وظائف أطراف دائرة التحكم:-

النوع	الرمز	اسم الطرف	وصف وتوضيح
الاتصال	485A	485+	RS485 مدخل اتصال ،متوافق مع Modbus ودا بروتوكول اتصال .
	485B	485-	
دخل وخرج رقمي	DI1~DI4	ادخال رقمي	خيارات الادخال مصدر أو مستلم يتم ضبطها ب وصلة تحويل JUMPER
	DI5	مدخل رقمي -أطراف ادخال نبضات عالية السرعة	الخصائص العامة لأطراف الادخال الرقمية لقطر نبضات أقصى تردد للادخال 100 كيلو هرتز
	DO1	خرج رقمي 1	خرج مجمع مفتوح أقصى سعة =50ملي امبير
	FM	خرج تناظري 2	خرج مجمع مفتوح أقصى سعة =50ملي امبير ممكن تختار ك خرج قطر نبضات حتي 100 كيلو هرتز

ادخال واخراج تناظري	AI1	ادخال تناظري 1	نطاق جهد الدخل: 0V ~ 10V مقاومة الدخل: 22 كيلو
	AI2	ادخال تناظري 2	نطاق جهد الدخل: 0 ~ 10V or 4 ~ 20mA. مقاومة الدخل: 22K, jumper J8 وصله
	AO1	خرج تناظري 1	نطاق الخرج: 0 ~ 10V or 0 ~ 20mA,select by jumper J5
	AO2	خرج تناظري 2	نطاق الخرج: 0 ~ 10V or 0 ~ 20mA,select by jumper J5
اشارة تأريض مصدر الطاقة	10V	مصدر طاقة تناظري	تيار الخرج: 20mA دقة: 2%
	GND	أرضي تناظري	ارضي باشارة تناظرية
	24V	مصدر طاقة المستخدم	دقة: ±15%
	COM	أرضي رقمي	ارضي اشارة رقمية
خرج رلييه الحالة	T1/A, T1/B, T1/C	رلييه 1	TA/TB وضع الاغلاق الطبيعي normal Close TA/TC وضع مفتوح طبيعي normal open سعة الدرايف العاكس 3A, 25VAc, COSØ=0.4 ; 30Vdc, 1A
	T2/A, T2/B, T2/C	رلييه 2 (2 relay)	TA/TB normal close, TA/TC normal open ; Driving capability: 25VAc, 3A, COSØ=0.4 ; 30Vdc, 1A

ملاحظة: في توصيل قصير بين DI1 و COM قبل مغادرة المصنع. لو القاطع الرئيسي شغال والعاكس محافظ علي وضع الطاقة، هيبدا يقفل ويشغل آليا (اتوماتيك).العاكس هيشغل طبقا للخطوات التالية :-

- 1-مفتاح الطاقة للعاكس يشغل، قاطع التيار المستمر متصل والتبديل للطاقة من طرف المنظومة الشمسية .
 - 2-الخلايا الشمسية هتنتج طاقه مع شروقه الشمس وتمدها للعاكس .
 - 3-العاكس هيفحص جهد الدايرة المفتوحة للخلايا ويحاول يشغل المضخه، لو الجهد اقل من جهد السبات الانفرتر هيرجع sleep يقف ويرجع يشغل لم الجهد يزيد .
- في وقت المضخه هتشتغل بسرعه صغيرة،لو السرعه قلت لأقل سرعه الانفرتر هيتوقف وينتظر التشغيل .

الفصل السادس التشغيل والمراقبة

6.1-التوصيل طبقا للمخطط :-

تأكد جيدا من طاقة الدخول وجهد الدخول .وصل طرفي الطاقة من الخلايا لل R & T أطراف العاكس.أو وصلهم ل P+,N- تأكد من القطبية ولو الدخول تيار متناوب وصله ل R,S,T .

- الموديل 2S/2T ،التي تستخدم للمحركات المتناوبة أحادية الطور 220 فولت تحتاج Vmp is 310VDC, Voc is 350Voc,
- موديل 4T ،تستخدم للمحركات المتناوبة 380 فولت تحتاج Vmp is 540VDC, Voc is 620VDC.


يجب اتباع الجهد المنخفض من توحيد طاقة المتناوبة الي طاقه مستمرة .

$$Vmp=v2*220V=310VDC \text{ for } 220VAC \text{ pumps, } Voc=1.15=350VDC.$$

$$Vmp=v2*380V=540VDC \text{ for } 380VAC \text{ pumps, } Voc=1.15=620VDC$$

الطاقة الكلية الداخلة من الخلايا يجب أن تكون أكبر بمقدار 1.3 او 1.5 مرة من طاقة المضخة.وقدرة العاكس أكبر أو نفس قدرة المضخة .

- لا تشغل مصدر الطاقة (المنظومة الشمسية أو طاقة متناوبة من الشبكة) في نفس الوقت ،قبل توصيل دايود (موحد)قبل أطراف P+ , P-(N-)، لأنه لا توجد حماية عكس القطبية لدخل التيار المستمر.



6.2-تأكد من صحة التوصيل وشغل المفتاح 2 —Q2 إذن العاكس هيشغل .

6.3-تأكد منأن المضخة في وضع التحكم نشط ،2=PE-00، MPPT، في الوضع الافتراضي ،واضبط جهد الدارة المفتوحة Voc (d0-02) to PE-03 لو احتجت .

- 6.4- اضبط مجموعة معاملات المضخة (P2.01 to P2.06) P2 طبقا للبيانات المكتوبة عليها .
- 6.5- قم بتأكيد الأمر قيد التشغيل إذا تم تعيينه بواسطة لوحة مفاتيح التأكد. (P0-02=0) .
- 6.6- افحص اتجاه تشغيل المضخة إذا كان صحيح أو لا ،لو الاتجاه خاطئ ،من فضلك بدل طرفي من توصيلات المضخة .أو اضبط P8.13=0 (اجعل الاتجاه معكوس).
- 6.7- افحص معدل تصريف الماء ،والتردد إذا جيد أو لا .المستخدم قادر علي تهيئة PE04 الي PE13 .
- 6.8- لو عاوز وظيفة قفل وتشغل آلي ،يجب ضبط قناة الأمر بواسطة الاطراف P0-02=1 .
- 6.9- المستخدم يمكن تهيئة بعض الحماية مثل التشغيل الجاف ،تردد الايقاف المنخفض ،منحني ال P,Q — PE16 الي PE40 .
- 6.10- لتشغيل مضخات التزامنية ذو المغناطيسية الدائمة ،المستخدم يجب أن يختار وضع التحكم مسار مفتوح (P0-01=1) لتشغيل .قبل اختيار وضع التحكم بمسار مفتوح ،يجب علينا الحصول علي المعاملات الدقيقة للمحرك عن طريق أداء ضبط المحرك .
- اجراء ضبط المحرك PMSM :-

- اضبط P0.01=1 لاختيار وضع التحكم الغير مستحث لحلقة مفتوحة للمحرك .
- توجيه مجموعة معاملات المحرك (P1-20 to P1.00) ،اضبط P1.37=11 الضبط الالي للمحرك الساكن ،بعد الضبط الالي العاكس يستطيع تشغيل محركات PMSM بكفاءة عالية .



ملحوظه

- ممنوع توصيل أطراف القوة لأطراف الخرج U,V,W للعاكس ،غير ذلك هيدمر العاكس
- افحص اتجاه تشغيل المضخة إذا كان صحيح أو لا ،لو الاتجاه خاطئ ،من فضلك بدل طرفي فقط من توصيلات الاطراف الثلاثة للمضخة.
- الطاقة الكلية الداخلة من الخلايا يجب أن تكون أكبر بمقدار 1.3 أو 1.5 مرة من طاقة المضخة.وقدره العاكس أكبر أو نفس قدرة المضخة .
- يجب التأكد من استخدام محركات ذاتية القيادة لمضخات PMSM .فهو هام جدا لهذه المضخات .المستخدم ممكن يفحص P1-20 لو لديه أي تعديل بعد الضبط الالي AUTO TUNING لو هذه المعاملات غير صحيحه للمضخة من فضلك عدلها طبقا لمواصفات الموتور .

6.11-مخطط التشغيل :-ملاحظة

- 1- المستخدم ممكن يستخدم العاكس كعاكس متغير التردد.ويستخدم في تردد وعزم محركات المتناوبة،وجميع وظائف العاكس متاحة . FE00=0 .
 - 2- اضبط جهد الدارة المفتوحة للخلايا (PE-03=Voc) PE-03 ،d0-02 بواسطة فحص القيمة أو قياسها.
 - 3- اضبط وظيفة التشغيل الجاف PE22 ،لحماية المضخة من نقص الماء في البئر .
- اضبط وظيفة التردد المنخفض للمضخات لا تسمح لتشغيل في حماية السرعات الصغيرة ب PE19 الي PE2 .اضبط حماية المضخات من زيادة للتيار ب PE25 و PE26 .اضبط وظيفة الطاقة المنخفضة حتي لا تسمح بتشغيل المضخة بطاقة منخفضة .(PE28 to PE30) .متوافق مع الاشارات الرقمية والتناظرية للفحص الكامل لخزات الماء.المستخدم ممكن يحصل عن معلومات التصريف والتصريف اليومي والطاقة المولدة والطاقة المنتجة اليومية من خلال ضبط منحني PQ .
- PE39 to PE38) واحصل علي مراقبة من U0 13 to U0 19 ،يوفر GPRS مراقبة عن بعد، وتحكم عن بعد، تاريخ تسجيل البيانات ووظيفة ضبط المعاملات البعيدة.

SG600 series solar pump inverter operation manual



الفصل السابع قائمة المعاملات البسيط

جدول وصف الرموز:-

- “√” توضح ان المعاملات ممكن تتغير في التشغيل والايقاف.
 “/” توضح أن المعاملات ممكن تتغير في وضع الايقاف ولا يمكن التغير في وضع التشغيل.
 “●” يوضح المعامل الابتدائي مرتبط بنموذج المحرك
 كل المعاملات للمتكررات المتناوبة في القائمة في الاسفل، ليست فقط للتحكم في المضخات الشمسية ولكن أيضا للتحكم في سرعة وعزم الموتور .
 “*” ضبط المصنع، لا يسمح للمستخدم بضبطه.
 وظائف التحكم بماملات الخلايا الشمسية موضحة باللون الأزرق.

Function code	Name	Setting range	Factory setting	Modifi cation
P0 Basic function parameters				
P0-00	G/P model display	1: G type (Heavy duty) 2: P type (pumps, fans load duty)	Per model	●
P0-01	The first motor control mode	0:VF control 1:Sensorless vector control without PG card feedback 2: Sensor vector control with PG card feedback 3: 2 wires output for 1 phase pump 4: 3 wires output for 1 phase pump (if remove starting capacitor and running capacitor, please select 4. If only remove starting capacitor or difficult to remove starting and running capacitors. Please select 3).	0	×
P0-02	Command mode	0: Keypad (LED OFF) 1:Terminal command (LED ON) 2: RS485 communication (LED flash)	0	√
P0-03	Main frequency reference source X	0: Set by P0-08 of keypad, UP/DOWN setting not saved after power down. 1: Set by P0-08 of keypad, UP/DOWN setting memorized power down. 2: Analog AI1 3: Analog AI2 4: Keypad potentiometer 5: PULSE trains frequency reference (DI5) 6: Multiple step command reference 7: Simple PLC	0	×

		8. PID 9: RS485 communication		
P0-04	Auxiliary frequency reference source Y	As same as P0-03 (main frequency reference source X)	0	×
P0-05	The auxiliary frequency source Y range basic reference when superposition	0:Relative to the maximum frequency 1:Relative to frequency source X	0	✓
P0-06	The auxiliary frequency source Y range when superposition	0%~150%	100%	✓
P0-07	Frequency source selection when superposition	Unit's digit: frequency source selection 0: main frequency source 1:Arithmetic result of main and auxiliary operation (arithmetic relationship operation depends on ten's digit) 2: Switchover between main frequency X source and auxiliary source Y 3: Switchover between main source X and arithmetic operation between of main source X and auxiliary source Y. 4: Switchover between auxiliary source Y and arithmetic operation between of main source X and auxiliary source Y Ten's digit : The arithmetic operation relationship between main and auxiliary. 0: main + auxiliary 1: main - auxiliary 2: Maximum of X and Y 3: Minimum of X and Y	00	✓
P0-08	Preset frequency	0.00Hz~Maximum (P0-10)	50.00Hz	✓
P0-09	Running direction	0: the same direction 1: the opposite direction	0	✓
P0-10	Maximum frequency	50.00Hz~600.00Hz	50.00Hz	×
P0-11	Upper limit frequency source	0: P0-12 1: AI1 2: AI2 3: Potentiometer of keypad 4: PULSE trains 5: Rs485 communication	3	×
P0-12	Upper limit frequency source	Lower limit frequency P0-14~Maximum frequency P0-10	50.00Hz	✓

P0-13	Upper limit frequency offset	0.00Hz~Maximum frequency P0-10	0.00Hz	√
P0-14	Lower limit frequency	0.00Hz~Maximum frequency P0-12	0.00Hz	√
P0-15	Carrier frequency	0.5kHz~16.0kHz	Per model	√
P0-16	Carrier frequency auto adjusting with temperature	0: Not 1: Yes	1	√
P0-17	Acceleration time 1	0.00s~650.00s(P0-19=2) 0.0s~6500.0s(P0-19=1) 0s~65000s(P0-19=0)	Per model	√
P0-18	Deceleration time 1	0.00s~650.00s(P0-19=2) 0.0s~6500.0s(P0-19=1) 0s~65000s(P0-19=0)	Per model	√
P0-19	Unit of acceleration /deceleration time	0: 1s 1: 0.1s 2: 0.01s	1	×
P0-20	The balance factory for 1 phase pump driving (3 phase output)	0.00 ~2.00	1.0	×
P0-21	The offset of auxiliary frequency source when perform superposition	0.00Hz~Maximum frequency F0-10	0.00Hz	√
P0-22	Frequency resolution	1: 0.1Hz 2: 0.01Hz	2	×

P0-23	Memory selection when frequency reference is set by digital	0: Not save 1: save	0	√
P0-24	Motor parameter group	0: Motor parameters group 1 1: Motor parameters group 2	0	×
P0-25	The reference frequency of Acceleration/ deceleration time	0: Maximum frequency (P0-10) 1: setting frequency 2: 100Hz	0	×
P0-26	UP/DOWN of reference	0: Running frequency 1: Set frequency	0	×
P0-27	Frequency source and command binding	Unit digit: Frequency source is bound by keypad command 0: No bonding 1: frequency is set by digital 2: AI1 3: AI2	0000	√

		4: potentiometer of keypad 5: PULSE train (DI5) 6: multi-step frequency 7: Simple PLC 8: PID 9: Communication Ten digit: Frequency source is bound by terminals Hundreds digit: Frequency source is bound by communication Thousands of digit: Automatic run Binding frequency source selection		
P0-28	Serial communication protocol selection	0: Modbus protocol	0	√

P1 First motor parameters group				
P1-00	Motor type	0:General asynchronous motor 1:Variable frequency asynchronous motor 2. Permanent magnet synchronous motor	0	×
P1-01	Rated power of motor	0.1KW~1000.0KW	Per model	×
P1-02	Rated voltage of motor	1V~2000V	Per model	×
P1-03	Rated current of motor	Inverter power <= 55KW: 0.01A~655.35A Inverter power > 55KW: 0.1A~6553.5A	Per model	×
P1-04	Rated frequency of motor	0.01Hz~Maximum frequency	Per model	×
P1-05	Rated speed of motor	1rpm~65535rpm	Per model	×
P1-06	Asyn. Motor Stator resistance	Inverter power <= 55KW: 0.001Ω~65.535Ω Inverter power > 55KW: 0.0001Ω~6.5535Ω	Auto tuning	×
P1-07	Asyn. motor rotor resistance	Inverter power <= 55KW: 0.001Ω~65.535Ω Inverter power > 55KW : 0.0001Ω~6.5535Ω	Auto tuning	×
P1-08	Asyn. motor leakage inductance	Inverter power <= 55KW: 0.01mH~655.35mH Inverter power > 55KW: 0.001mH~65.535mH	Auto tuning	×

P1-09	Asyn. motor mutual inductance	Inverter power ≤ 55KW: 0.1mH~6553.5mH Inverter power > 55KW: 0.01mH~655.35mH	Auto tuning	×
P1-10	Asyn. motor no-load current	Inverter power ≤ 55KW: 0.01A~F1-03 Inverter power > 55KW: 0.1A~F1-03	Auto tuning	×
P1-16	Synchronous motor stator resistance	Inverter power ≤ 55KW: 0.001Ω~65.535Ω Inverter power > 55KW: 0.0001Ω~6.5535Ω	Auto tuning	×
P1-17	Synchronous motor D-axis inductance	Inverter power ≤ 55KW: 0.01mH~655.35mH Inverter power > 55KW: 0.001mH~65.535mH	Auto tuning	×
P1-18	Synchronous motor Q axis inductance	Inverter power ≤ 55KW: 0.01mH~655.35mH Inverter power > 55KW: 0.001mH~65.535mH	Auto tuning	×
P1-20	Synchronous motor back electromotive force	0.1V~6553.5V	Auto tuning	×
P1-27	Number of encoder lines	1~65535	1024	×
P1-28	Encoder type	0: ABZ incremental encoder 1: UVW incremental encode 2: Rotary transformer 3: Sine and cosine encoders 4: Provincial line UVW encoder	0	×
P1-30	ABZ incremental encoder phase sequence	0: Forward 1: Reverse	0	×

P1-31	Encoder installation angle	0.0~359.9°	0.0°	×
P1-32	Reserve	0	0	×
P1-33	Reserve	0	0	×
P1-34	Number of pole pairs of rotary transformers	1~65535	1	×
P1-36	Speed feedback PG disconnection Detection time	0.0: on operation 0.1s~10.0s	0.0	×
P1-37	Auto tuning mode selection	0: no operation 1: Asynchronous motor still tunes 2: Asynchronous motor complete tuning 11: Synchronous motor tuning with load 12: Synchronous motor with no-load tuning	0	×

P2 group The first motor vector control parameters				
P2-00	Speed loop proportional gain 1	1~100	30	√
P2-01	Speed loop integral time 1	0.01s~10.00s	0.50s	√
P2-02	Switching frequency 1	0.00~P2-05	5.00Hz	√
P2-03	Speed loop proportional gain 2	1~100	20	√
P2-04	Speed loop integral time 2	0.01s~10.00s	1.00s	√
P2-05	Switching frequency 2	P2-02~Maximum frequency	10.00Hz	√
P2-06	Slip compensation coefficient	50%~200%	100%	√
P2-07	Speed loop filter time constant	0.000s~0.100s	0.000s	√
P2-08	Vector control over excitation gain	0~200	64	√
P2-09	Upper limit of torque source selection in speed control mode	0: set by P2-10 1: AI1 2: AI2 3: Potentiometer of keypad 4: PULSE train 5: communication 6: MIN(AI1,AI2) 7: MAX(AI1,AI2) The full range of 1-7 option is correspond to P2-10	0	√
P2-10	Upper limit of torque digital setting in speed control mode	0.0%~200.0%	150.0%	√

P2-13	Excitation adjustment proportional gain	0~60000	2000	√
P2-14	Excitation adjustment integral gain	0~60000	1300	√
P2-15	Torque adjustment proportional gain	0~60000	2000	√
P2-16	Torque adjustment integral gain	0~60000	1300	√
P2-17	Observer Gain	0.1% - 999.9%	30.0%	√
P2-18	Observer Filter Time	0.1 - 100.0ms	4.0ms	√
P2-19	AM motor pre-Flux time	0 - 9999ms	300ms	√

P2-20	PM sensorless start mode	0:Start directly 1: Detect flux before start 2: Dc-inject before start	2	×
P2-21	Dc-inject current	0.0% - 200.0%	30.0%	√
P2-22	MTPA gain	0.0% - 999.9%	80.0%	√
P2-23	MTPA filter time	1ms - 9999ms	100ms	√
P2-24	PM Flux weak current	0.1% - 200.0%	0	√
P2-25	Flux weak forward Gain	0.1% - 999.9%	0	√
P2-26	Flux weak feedback Gain	0 - 9999	1000	√
P2-27	Flux weak integral gain	0 - 9999	1000	√
P2-30	PM stability Gain	0.1% - 100.0%	10.0%	√
P2-31	PM current Gain	0.1 - 20.0	3.0	√
P2-32	PM magnetic depth	0.1% - 500.0%	60.0%	√
P2-33	PM magnetic Gain	0 - 5000	1000	√
P2-34	PM magnetic integral	0 - 5000	1000	√
P2-35	Dc-inject time	0 - 9999	500	√
P2-36	Dc-inject low freq.	0.0 - 100.0%	10.0%	√
P2-37	Dc-inject high freq.	0.0 - 100.0%	20.0%	√

P3 group V/F control parameters				
P3-00	VF curve setting	0: Linear V / F curve 1: Multi-point V / F curve 2: Square V / F curve 3: 1.2 power V / F 4: 1.4 power V / F 6: 1.6 power V/F 8: 1.8 power V/f 10: VF completely separation mode 1 11: VF Semi-separated separation mode 2	0	×
P3-01	Torque booster	0.0%: (Automatic torque boost) 0.1%~30.0%	Per model	√
P3-02	Torque boost cut-off frequency	0.00Hz~Maximum frequency	50.00Hz	×
P3-03	Multipoint VF frequency point 1	0.00Hz~P3-05	0.00Hz	×
P3-04	Multipoint VF voltage point 1	0.0%~100.0%	0.0%	×
P3-05	Multipoint VF frequency point 2	P3-03~P3-07	0.00Hz	×

P3-06	Multipoint VF voltage point 2	0.0%~100.0%	0.0%	×
P3-07	Multipoint VF frequency point 3	P3-05~Motor rated frequency(F1-04)	0.00Hz	×
P3-08	Multipoint VF voltage point 3	0.0%~100.0%	0.0%	×
P3-09	VF Slip compensation gain coefficient	0.0%~200.0%	100.0%	√
P3-10	VF over excitation gain	0~200	100	√
P3-11	VF oscillation suppression gain	0~100	50	√
P3-13	VF separate voltage source	0: Set by digital (F3-14) 1: AI1 2: AI2 3: Potentiometer of keypad 4: PULSE train (DI5) 5: Multiple speed command 6: Simple PLC 7: PID 8: Communication Note: 100.0% corresponds to the motor rated voltage	0	√
P3-14	VF separate voltage digital setting	0V~Rated motor voltage	0V	√
P3-15	acceleration time of VF separate	0.0s~1000.0s Note: Indicates the deceleration time when 0V changes to the motor rated voltage	0.0s	√

P4 group Input terminals

P4-00	DI1 terminals function selection	0: no operation 1: Forward running or running command 2: Reverse running REV or forward/reverse running direction selection (note: when set for 1 or 2 parameter, please reference to P4-11 function introduction) 3: 3 line control mode 4: Forward Jog (FJOG) 5: Reverse Jog (RJOG) 6: Terminal UP 7: Terminal DOWN 8: Free stop 9: Fault reset (RESET)	1	×
P4-01	DI2 terminals function selection		4	×
P4-02	DI3 terminals function selection		9	×
P4-03	DI4 terminals function selection		12	×
P4-04	DI5 terminals function selection		13	×
P4-05	Reserve		0	×
P4-06	Reserve		0	×

SG600 series solar pump inverter operation manual

P4-07	Reserve	10: Run pause	0	×
P4-08	Reserve	11: External fault normal open input	0	×
P4-09	Reserve	12: Multiple step terminals 1 13: Multiple step terminals 2 14: Multiple step terminals 3 15: Multiple step terminals 4 16: Acceleration/ deceleration selection terminals 1 17: Acceleration/ deceleration selection terminals 2 18: Frequency source switch 19: UP/DOWN setting reset (terminals or keypad) 20: Running command terminals switch 21: Acceleration/deceleration forbidden 22: PID pause 23: PLC status reset 24: Swing frequency pause 25: Counter input 26: Counter reset 27: length counting input 28: length reset 29: Torque control forbidden 30: PULSE train frequency input (only for DI5 valid) 31: Reserve 32: Starting DC braking 33: External fault normal close input 34: Frequency change enable	0	×
		34: Frequency change enable 35: Change PID direction 36: External parking terminal 1 37: Control command switch over terminal2 38: PID integral pause 39: Switchover between frequency source X and preset frequency 40: Switchover between frequency source Y and preset frequency 41: Motor selection terminals 1 42: Motor selection terminals 2 43: PID parameter switchover 44: User define fault 1 45: User define fault 2 46: Speed control /Torque control switchover		

		47: Emergency stop 48: External parking terminal 2 49: DC braking in deceleration 50: current running time res 51: Water tank full detect 1/ single point detect 52: Water tank full detect 2/ single point detect 53: MPPT tracking stop/ solar pump control disable.		
P4-10	DI filter time	0.000s~1.000s	0.010s	✓
P4-11	Terminals command mode	0: Two line control 1 1: Two line control 2 2: 3 line control 1 3: 3 line control 2	0	✗
P4-12	Terminals UP/DOWN Change ratio	0.001Hz/s~65.535Hz/s	1.00Hz/s	✓
P4-13	AI curve 1 minimum input	0.00V~P4-15	0.00V	✓
P4-14	AI curve 1 minimum input corresponding setting	-100.0%~+100.0%	0.0%	✓
P4-15	AI curve 1 Max. input	P4-13~+10.00V	10.00V	✓
P4-16	AI curve 1 Max input corresponding setting	-100.0%~+100.0%	100.0%	✓
P4-17	AI1 filter time	0.00s~10.00s	0.10s	✓
P4-18	AI curve 2 minimum input	0.00V~P4-20	0.00V	✓
P4-19	AI curve 2 minimum input corresponding setting	-100.0%~+100.0%	0.0%	✓

P4-20	AI curve 2 Max. input	P4-18~+10.00V	10.00V	✓
P4-21	AI curve 2 Max input corresponding setting	-100.0%~+100.0%	100.0%	✓
P4-22	AI2 filter time	0.00s~10.00s	0.10s	✓
P4-23	AI curve 3 minimum input	-10.00V~P4-25	-10.00V	✓
P4-24	AI curve 3 minimum input corresponding setting	-100.0%~+100.0%	-100.0%	✓
P4-25	AI curve 3 Max. input	P4-23~+10.00V	10.00V	✓
P4-26	AI curve 3 Max input corresponding setting	-100.0%~+100.0%	100.0%	✓
P4-27	AI3 filter time	0.00s~10.00s	0.10s	✓
P4-28	PULSE Min. input	0.00kHz~P4-30	0.00kHz	✓

P4-29	PULSE Min. input corresponding setting	-100.0%~100.0%	0.0%	✓
P4-30	PULSE Maximum input	P4-28~100.00kHz	50.00k Hz	✓
P4-31	PULSE Max. Input corresponding setting	-100.0%~100.0%	100.0%	✓
P4-32	PULSE filter time	0.00s~10.00s	0.10s	✓
P4-33	AI Curve selection	Units' digit: All curve selection 1: Curve 1 (2 point, see P4-13~P4-16) 2: Curve 2 (2 point, see P4-18~P4-21) 3: Curve 3 (2 point, see P4-23~F4-26) 4: Curve 4 (4 point, see A6-00~A6-07) 5: Curve 5 (4 point, see A6-08~A6-15) Ten's digit: AI2 curve selection, as above Hundred's digit: Curve set by potentiometer of keypad, as above	321	✓
P4-34	When AI input is less than minimum setting selection	Units' digit: AI 1 is less than minimum input Set selection 0: Corresponds to the minimum input setting 1:0.0% Ten's digit: A2 is less than minimum input Set selection, as above Hundred's digit: Potentiometer less than Min. Input selection, as above	000	✓
P4-35	DI1 Relay time	0.0s~3600.0s	0.0s	×
P4-36	DI2 Relay time	0.0s~3600.0s	0.0s	×
P4-37	DI3 Relay time	0.0s~3600.0s	0.0s	×
P4-38	DI terminal effective mode choose 1	0: Enable in High level 1: Enable in low level Digits: DI1 Ten's: DI2 Hundred's: DI3 Thousand's:DI4 Ten thousand's: DI5	00000	×
P4-39	DI terminal effective mode choose 2	0: Enable in High level 1: Enable in low level Digits: DI6 Ten's: DI7 Hundred's: DI8 Thousand's: DI9 Ten thousand's: DI10	00000	×

P5 Group Output terminals				
P5-00	FM terminals output mode selection	0: High speed pulse output (FMP) 1: Digital output (FMR)	0	√
P5-01	FMR output function selection	0: No output 1: Frequency inverter running	0	√
P5-02	Relay 1 function selection	2: Fault output (Free stop fault)	2	√
P5-03	Relay 2 function selection	3: FDT1 Frequency level detect output	0	√
P5-04	DO1 output function selection	4: Frequency reach 5: Zero speed running (no output when stop)	1	√
P5-05	Extension card DO2 Output selection	6: Motor overload pre-alarm 7: Inverter overload pre-alarm 8: Preset counting reach 9: Specify counting reach 10: Length reach 11: PLC cycle running finish 12: Cumulative run time arrives 13: Frequency limit 14: Torque limit 15: Ready to run 16: A11>A12 17: Upper limit frequency arrives 18: Lower limit frequency arrives (relative to running) 17: Upper limit frequency arrives 18: Lower limit frequency arrives 19: Under voltage status output 20: Communication setting 21: Positioning finish (reserve) 22: Positioning approach (Reserve)	4	√
		22: Positioning approach (Reserve) 23: Zero speed running 2(output when in stop as well) 24: Accumulated power up time arrives 25: Frequency level detection FDT2 output 26: Output when frequency 1 reaches 27: Output when frequency 2 reaches 28: Output when current 1 reaches 29: Output when current 2 reaches 30: Output when timing up 31: A11 input over limit 32: Under loading 33: reverse running 34: Zero current state		

		35: Module temperature arrives 36: Output current is exceeded 37: Lower frequency arrival (output when stop as well) 38: Alarm output (all faults) 39: Motor over temperature warning 40: Current running time arrives 41: Fault output (for free stop failure and under voltage is not output)		
P5-06	FMP output function selection	0: Running frequency 1: Setting frequency	0	√
P5-07	AO1 output function selection	2: Output current 3: Output torque (Absolute value of torque)	0	√
P5-08	AO2 output function selection	4: Output power 5: Output voltage 6: Pulse input (100% corresponds to 100.0Hz) 7: AI1 8: AI2 9: Keyboard potentiometer 10: Length 11: Count value 12: Communication settings 13: Motor speed 14: Output current (100.0% corresponds to 1000.0A) 15: Output voltage (100.0% corresponds to 1000.0V) 16: Output torque (torque actual value)	1	√

P5-09	FMP maximum frequency	0.01kHz~100.00kHz	50.00k Hz	√
P5-10	AO1 zero bias coefficient	-100.0%~+100.0%	0.0%	√
P5-11	AO1 gain	-10.00~+10.00	1.00	√
P5-12	AO2 zero bias	-100.0%~+100.0%	0.0%	√
P5-13	AO2 gain	-10.00~+10.00	1.00	√
P5-17	FMR output relay time	0.0s~3600.0s	0.0s	√
P5-18	RELAY1 output relay time	0.0s~3600.0s	0.0s	√
P5-19	RELAY2 output relay time	0.0s~3600.0s	0.0s	√
P5-20	DO1 output relay time	0.0s~3600.0s	0.0s	√
P5-21	DO2 output relay time	0.0s~3600.0s	0.0s	√

P5-22	DO output terminal valid state selection	0: Positive logic 1: Negative logic Bits: FMR Ten's bit: RELAY1 Hundreds's bit: RELAY2 Thousands's bits: DO1 Ten thousands's bit;s: DO2	00000	√
P6 Group start and stop control				
P6-00	Starting mode	0: Directly start 1: start after speed tracking 2: Pre-excitation start (AC asynchronous machine)-	0	√
P6-01	Speed tracking mode	00: starts from stop frequency 1: starts at zero speed 2: Starting from the maximum frequency	0	×
P6-02	The speed of speed tracking	1~100	20	√
P6-03	Starting speed	0.00Hz~10.00Hz	0.00Hz	√
P6-04	Starting speed keeping time	0.0s~100.0s	0.0s	×
P6-05	Start DC braking current / pre-excitation current	0%~100%	0%	×
P6-06	Start DC braking time / pre-excitation time	0.0s~100.0s	0.0s	×
P6-07	Acceleration and deceleration mode	0: Linear acceleration / deceleration 1: S curve acceleration / deceleration A 2: S curve acceleration and deceleration B	0	×

P6-08	S curve starting section time ratio	0.0%~(100.0%-P6-09)	30.0%	×
P6-09	S curve finishing section time ratio	0.0%~(100.0%-P6-08)	30.0%	×
P6-10	Stop mode	0: Deceleration stop 1: free parking	0	√
P6-11	start frequency when in stop with DC braking	0.00Hz~Maximum frequency	0.00Hz	√
P6-12	Waiting time of stop with DC braking	0.0s~100.0s	0.0s	√
P6-13	Braking current when Stop with DC braking	0%~100%	0%	√
P6-14	DC braking time when stop	0.0s~100.0s	0.0s	√
P6-15	Brake usage ratio	0%~100%	100%	√

P7 Group keyboard and display				
P7-01	MF.K function button option	0: MF.K is invalid 1: Switchover between Operation panel command channel and remote command channel (terminal command channel or communication command channel) 2: Forward and reverse switching 3: Forward Jog 4: Reverse Jog	0	×
P7-02	STOP/RESET function	0: STOP/RES button enable only in operation panel control mode 1: STOP/RES button enable in any control mode	1	✓
P7-03	LED display parameters 1 in running mode	0000~FFFF Bit00: Running frequency 1(Hz) Bit01: Setting frequency (Hz) Bit02: DC bus voltage (V) Bit03: Output voltage (V) Bit04: Output current (A) Bit05: Output power (KW) Bit06: Output torque (%) Bit07: DI input status Bit08: DO output status Bit09: AI1 voltage (V) Bit10: AI2 voltage (V) Bit11: Voltage of potentiometer(V) Bit12: Counting Bit13: Length	1F	✓
		Bit13: Length Bit14: Load speed display Bit15: PID setting		
P7-04	LED display parameters 2 in running mode	0000~FFFF Bit00: PID feedback Bit01: PLC stage Bit02: PULSE input pulse train frequency (kHz) Bit03: Running frequency 2 (Hz) Bit04: Rest running time Bit05: AI1 before correction voltage (V) Bit06: AI2 before correction voltage (V) Bit07: operation panel potentiometer before correction voltage (V) Bit08: Line speed Bit09: Current power-on time (Hour)	0	✓

		Bit10: Current running time (Min) Bit11: PULSE train input pulse frequency (Hz) Bit12: Communication set point Bit13: Encoder feedback speed (Hz) Bit14: Main frequency X display (Hz) Bit15: Auxiliary Frequency Y Display (Hz)		
P7-05	LED display in stop mode	0000 ~ FFFF Bit00: Set frequency (Hz) Bit01: Bus voltage (V) Bit02: DI input status Bit03: DO output status Bit04: AI1 voltage (V) Bit05: AI2 voltage (V) Bit06: Operation panel potentiometer voltage (V) Bit07: Count value Bit08: Length value Bit09: PLC stage Bit10: Load speed Bit11: PID setting Bit12: PULSE train input pulse frequency (kHz)	33	√

P7-06	Load speed display factor	0.0001~6.5000	1.0000	√
P7-07	Heat sink of Inverter IGBT model temperature	0.0°C~100.0°C	-	●
P7-08	Heat sink of Inverter Rectifier temperature	0.0°C~100.0°C	-	●
P7-09	Cumulative run time	0h~65535h	-	●
P7-10	Products serial No.	-	-	●
P7-11	Software version No.	-	-	●
P7-12	The number of decimal places of load speed Displays	0: 0 decimal places 1: 1 decimal place 2: 2 decimal places 3: 3 decimal places	1	√
P7-13	Accumulated time since power on	0~65535 hour	-	●
P7-14	Cumulative power consumption	0~65535 KWh	-	●

P8 group Auxiliary function				
P8-00	Jog running frequency	0.00Hz~Maximum frequency	2.00Hz	√
P8-01	Jog acceleration	0.0s~6500.0s	20.0s	√
P8-02	Jog deceleration	0.0s~6500.0s	20.0s	√
P8-03	Acceleration time 2	0.0s~6500.0s	Per model	√
P8-04	Deceleration time 2	0.0s~6500.0s	Per model	√
P8-05	Acceleration time 3	0.0s~6500.0s	Per model	√
P8-06	Deceleration time 3	0.0s~6500.0s	Per model	√
P8-07	Acceleration time 4	0.0s~6500.0s	Per model	√
P8-08	Deceleration time 4	0.0s~6500.0s	Per model	√
P8-09	Jumping frequency 1	0.00Hz~Maximum frequency	0.00Hz	√
P8-10	Jumping frequency 2	0.00Hz~Maximum frequency	0.00Hz	√
P8-11	Jump frequency range	0.00Hz~Maximum frequency	0.01Hz	√
P8-12	Dead zone time of forward to reverse	0.0s~3000.0s	0.0s	√
P8-13	Reverse running enable	0: Allow 1: Forbidden	0	√
P8-14	Running mode when setting frequency is less than the lower limit frequency	0: Run at lower limit frequency 1: stop 2: Zero speed running	0	√
P8-15	Drop control	0.00Hz~10.00Hz	0.00Hz	√

P8-16	Set the cumulative power-up arrival time	0h~65000h	0h	√
P8-17	Set the cumulative running arrival time	0h~65000h	0h	√
P8-18	Start protection selection	0: Disable 1: Enable	0	√
P8-19	Frequency detection value (FDT1)	0.00Hz~Maximum frequency	50.00Hz	√
P8-20	Frequency detection hysteresis (FDT1)	0.0%~100.0% (FDT1 voltage level)	5.0%	√
P8-21	Frequency arrival detection amplitude	0.0%~100.0% (Maximum frequency)	0.0%	√

P8-22	Whether the jump frequency is valid during acceleration / deceleration	0: Invalid 1: Valid	0	√
P8-25	Switchover point between acceleration time 1 to acceleration time 2	0.00Hz~Maximum frequency	0.00Hz	√
P8-26	Switchover point between deceleration time 1 to deceleration time 2	0.00Hz~Maximum frequency	0.00Hz	√
P8-27	Terminal control prior	0 : Invalid 1: Valid	0	√
P8-28	Frequency detection value (FDT2)	0.00Hz~Maximum frequency	50.00Hz	√
P8-29	Frequency detection hysteresis (FDT2)	0.0%~100.0% (FDT2 voltage level)	5.0%	√
P8-30	Any arrival frequency detection value 1	0.00Hz~Maximum frequency	50.00Hz	√
P8-31	Any arrival frequency detection amplitude 1	0.0%~100.0% (Maximum frequency)	0.0%	√
P8-32	Any arrival frequency detection value 2	0.00Hz~Maximum frequency	50.00Hz	√
P8-33	Any arrival frequency detection amplitude 2	0.0%~100.0% (Maximum frequency)	0.0%	√
P8-34	Zero current detection level	0.0%~300.0% 100.0% corresponds to the motor rated current	5.0%	√

P8-35	Zero current detection delay time	0.01s~600.00s	0.10s	√
P8-36	Output current over limit	0.0% (No detect) 0.1%~300.0% (Rated current)	200.0%	√
P8-37	Output current over limit detect relay time	0.00s~600.00s	0.00s	√
P8-38	Any arrival current 1	0.0%~300.0%(Motor rated current)	100.0%	√
P8-39	Any arrival current 1 detect amplitude	0.0%~300.0% (Motor rated current)	0.0%	√
P8-40	Any arrival current 2	0.0%~300.0% (Motor rated current)	100.0%	√
P8-41	Any arrival current 2 detect amplitude	0.0%~300.0% (Motor rated current)	0.0%	√
P8-42	Timing function selection	0: Invalid 1: Valid	0	√
P8-43	Timing of run time	0: Set by P8-44	0	√

	selection	1: AI1 2: AI2 3: Potentiometer of operation panel The range of analog input corresponds to P8-44		
P8-44	Timing value setting of running time	0.0Min~6500.0Min	0.0Min	✓
P8-45	Lower limit of AI1 input voltage protection	0.00V~P8-46	3.10V	✓
P8-46	Upper limit of AI1 input voltage protection	P8-45~10.00V	6.80V	✓
P8-47	IGBT Module temperature arrives	0℃~100℃	75℃	✓
P8-48	Cooling fan control	0: Working in running 1: Working after power up	0	✓
P8-49	Wake up frequency	Sleep frequency (P8-51)~Maximum (P0-10)	0.00Hz	✓
P8-50	Wake up delay time	0.0s~6500.0s	0.0s	✓
P8-51	Sleep frequency	0.00Hz~Wake up frequency (P8-49)	0.00Hz	✓
P8-52	Sleep relay time	0.0s~6500.0s	0.0s	✓
P8-53	Current running arrival time setting	0.0~6500.0 min.	0.0Min	✓

P9 group Fault and protection				
P9-00	Motor overload protection selection	0: Prohibited 1: Allow	1	✓
P9-01	Motor overload protection gain	0.20~10.00	1.00	✓
P9-02	Motor overload pre-warning coefficient	50%~100%	80%	✓
P9-03	Overvoltage stall gain	0~100	100	✓
P9-04	Overvoltage stall protection voltage	120%~150%	135%	✓
P9-05	Over-current stall gain	0~100	20	✓
P9-06	Overcurrent stall protection current	100%~200%	150%	✓
P9-07	Ground short circuit protection options when power on	0: Invalid 1: Valid	1	✓

P9-09	Number of automatic reset times	0~20	0	√
P9-10	DO (digital output) when fault alarm auto reset	0: No action 1: Action	0	√
P9-11	Fault auto reset interval time	0.1s~100.0s	1.0s	√
P9-12	Input phase loss/ contactor pull protection selection	Bit: Input phase loss protection selection Ten: Contactor pull protection options 0: Prohibited 1: Allow	11	√
P9-13	Output phase loss protection	0: Prohibited 1: Allow	1	√
P9-14	First failure alarm type	0: No fault 1: Reserved 2: Over current in acceleration 3: Over current in deceleration 4: Over current in constant speed during 5: Over voltage in acceleration 6: Over voltage in deceleration 7: Over voltage in constant speed during 8: Buffer resistance overload 9: Under voltage 10: Inverter overload 11: Motor overload 12: Input phase loss	—	●
P9-15	Second fault alarm type	13: Output phase loss 14: IGBT Module overheating 15: External fault 16: Communication error 17: Contactor is abnormal 18: Current detection is abnormal 19: Motor tuning abnormal 20: Encoder / PG card is abnormal 21: Parameter read and write exception 22: Inverter hardware abnormality 23: Motor to ground short circuit 24: Reserved 25: Reserved	—	●
P9-16	The third (latest one) type of failure	26: Running time arrives 27: User defined fault 1 28: user defined fault 2 29: Power-up time arrives	—	●

		30: Under load 31: PID feedback is missing in running 40: Fast current limit timeout 41: Motor switch in running 42: The speed deviation is too big 43: Motor over speed 45: Motor over temperature 51: Initial position error		
P9-17	Frequency at when the third (last) failure frequency	—	—	●
P9-18	Current at when the third (last) failure frequency	—	—	●
P9-19	DC bus voltage at when the third (last) failure frequency	—	—	●
P9-20	Input terminals status at when the third (last) failure frequency	—	—	●
P9-21	Output terminals status at when the third (last) failure frequency	—	—	●
P9-22	Inverter status when the third (last) failure frequency	—	—	●
P9-23	Power up time when the third (last) failure frequency	—	—	●
P9-24	Running time when the third (last) failure frequency	—	—	●

P9-27	Frequency at when the second failure	—	—	●
P9-28	Current at when the second failure	—	—	●
P9-29	DC bus voltage at when the second failure	—	—	●
P9-30	Input terminals status at when the second failure	—	—	●
P9-31	Output terminals status at when the second failure	—	—	●
P9-32	Inverter status at when the second failure	—	—	●
P9-33	Power up time when the second failure	—	—	●

P9-34	Running time when the second failure	—	—	●
P9-37	Frequency at when the third failure	—	—	●
P9-38	Current at when the third failure	—	—	●
P9-39	DC bus voltage at when the third failure	—	—	●
P9-40	Input terminals status at when the third failure	—	—	●
P9-41	Output terminals status at when the third failure	—	—	●
P9-42	Inverter status at when the third failure	—	—	●
P9-43	Power up time when the third failure	—	—	●
P9-44	Running time when the third failure	—	—	●
P9-47	Fault protection action selection 1	Bit: Motor overload (11) 0: Free stop 1: Stop by stop mode setting 2: Continue to run Ten: Input missing (12) Hundreds: Output phase loss (13) Thousands of bits: external failure (15) Million: communication anomaly (16)	00000	✓

P9-48	Fault protection action selection 3	Bit: Encoder / PG card exception (20) 0: Free stop Ten: Function code read and write exception (21) 0: Free stop 1: Stop by stop mode setting Hundred places: reserved Thousands: Motor overheating (25) Million: run time arrival (26)	00000	✓
P9-49	Fault protection action selection 3	Bit: User defined fault 1 (27) 0: Free stop 1: Stop by stop mode 2: Continue to run Ten: User Defined Fault 2 (28) 0: Free Stop	00000	✓

		1: Stop by stop mode 2: Continue to run Hundreds: Power-up time arrives (29) 0: Free stop 1: Stop by stop mode 2: Continue to run Thousands of bits: (30) 0: Free stop 1: Deceleration stop 2: Skip to 7% of the rated motor frequency to continue running, restore to run with setting frequency after no missing load Million: PID feedback lost in running (31) 0: Free parking 1: Stop by stop mode 2: Continue to run		
P9-50	Fault protection action selection 4	Bit: the speed deviation is too large (42) 0: Free stop 1: Stop by stop mode 2: Continue to run Ten: Motor over speed (43) Hundred places: initial position error (51)	00000	✓
P9-54	Running frequency of continue running when fault alarm	0: Run at the current operating frequency 1: Run at set frequency 2: Run at the upper limit frequency 3: Run at the lower limit frequency 4: Run at an abnormal standby frequency	0	✓

P9-55	An abnormal standby frequency	0.0%~100.0% (100.0% corresponds to the maximum frequency P0-10)	100.0%	✓
P9-56	Motor temperature sensor type	0: No temperature sensor 1: PT100 2: PT1000	0	✓
P9-57	Motor overheat protection threshold	0℃~200℃	110℃	✓
P9-58	Motor overheat pre-warning threshold	0℃~200℃	90℃	✓
P9-59	Working action of Instantaneous power fail selection	0: Invalid 1: Deceleration 2: Deceleration stop	0	✓
P9-60	Judgment voltage of instantaneous power fail	80.0%~100.0%	90.0%	✓

	pause			
P9-61	Voltage recovery judgment time when instantaneous power fail	0.00s~100.00s	0.50s	✓
P9-62	Judgment voltage of instantaneous power failure action	60.0%~100.0%(Standard bus voltage)	80.0%	✓
P9-63	Load miss protection	0: Disable 1: Enable	0	✓
P9-64	Load miss detection level	0.0~100.0%	10.0%	✓
P9-65	Load miss detection time	0.0~60.0s	1.0s	✓
P9-67	Over speed detection	0.0%~50.0%(Max frequency)	20.0%	✓
P9-68	Over speed detection time	0.0s: No detect 0.1~60.0s	1.0s	✓
P9-69	Detection value of the speed deviation is too big	0.0%~50.0%(Max frequency)	20.0%	✓
P9-70	Detection time of speed deviation is too big.	0.0s: No detect 0.1~60.0s	5.0s	✓

PA Group PID function				
PA-00	PID reference source	0: PA-01 1: AI1 2: AI2 3: Keyboard potentiometer 4: PULSE train setting (DI5) 5: Communication reference 6: Multi-step instructions reference	0	✓
PA-01	PID value setting	0.0%~100.0%	50.0%	✓
PA-02	PID feedback source	0: AI1 1: AI2 2: Keyboard potentiometer 3: AI1-AI2 4: PULSE setting (DI5) 5: Communication reference 6: AI1 + AI2 7: MAX (AI1 , AI2) 8: MIN (AI1 , AI2)	0	✓
PA-03	PID working direction	0: Positive effect 1: Reverse effect	0	✓
PA-04	PID reference feedback range	0~65535	1000	✓
PA-05	Proportional gain Kp1	0.0~100.0	20.0	✓

SG600 series solar pump inverter operation manual

PA-06	Integral time Ti1	0.01s~10.00s	2.00s	√
PA-07	Differential time Td1	0.000s~10.000s	0.000s	√
PA-08	PID reversal cutoff frequency	0.00~Maximum frequency	2.00Hz	√
PA-09	PID deviation limit	0.0%~100.0%	0.0%	√
PA-10	PID differential limiting	0.00%~100.00%	0.10%	√
PA-11	PID reference given change time	0.00~650.00s	0.00s	√
PA-12	PID feedback filter time	0.00~60.00s	0.00s	√
PA-13	PID output filter time	0.00~60.00s	0.00s	√
PA-14	Reserve	-	-	√
PA-15	Proportional gain Kp2	0.0~100.0	20.0	√
PA-16	Integral time Ti2	0.01s~10.00s	2.00s	√
PA-17	Derivative time Td2	0.000s~10.000s	0.000s	√
PA-18	PID parameter switching condition	0: Do not switch 1: Switch via DI terminal 2: Automatic switching according to the deviation	0	√
PA-19	PID parameter switching deviation 1	0.0%~PA-20	20.0%	√
PA-20	PID parameter switching deviation 2	FA-19~100.0%	80.0%	√
PA-21	PID initial value	0.0%~100.0%	0.0%	√

PA-22	PID initial value hold time	0.00~650.00s	0.00s	√
PA-23	The maximum value of positive deviations for two output	0.00%~100.00%	1.00%	√
PA-24	The maximum value of reverse deviations for two output	0.00%~100.00%	1.00%	√
PA-25	PID integral property	Bit: Integral separation 0: Invalid 1: Valid Ten: Whether to stop the integral working after outputting to the limit 0: Continue integral working 1: Stop integral working	00	√
PA-26	PID feedback loss detection	0.0%:Do not judge feedback loss	0.0%	√

	value	0.1%~100.0%		
PA-27	PID Feedback loss detection time	0.0s~20.0s	0.0s	√
PA-28	PID calculating when stop	0: Don't execute calculating when stop 1: Execute PID calculating when stop	0	√
PB Group Wobble, Length and Count				
Pb-00	Wobble setting mode	0: Relative to center frequency 1: Relative to maximum frequency	0	√
Pb-01	Wobble amplitude	0.0%~100.0%	0.0%	√
Pb-02	Sudden jump frequency range	0.0%~50.0%	0.0%	√
Pb-03	Wobble cycle	0.1s~3000.0s	10.0s	√
Pb-04	Wobble of the triangular wave rise time	0.1%~100.0%	50.0%	√
Pb-05	Set length	0m~65535m	1000m	√
Pb-06	Actual length	0m~65535m	0m	√
Pb-07	Number of pulses per meter	0.1~6553.5	100.0	√
Pb-08	Set the count value	1~65535	1000	√
Pb-09	Specify the count value	1~65535	1000	√

PC Group multi-step instructions, simple PLC				
PC-00	Multi - step instructions 0	-100.0%~100.0%	0.0%	√
PC-01	Multi - step instructions 1	-100.0%~100.0%	0.0%	√
PC-02	Multi - step instructions 2	-100.0%~100.0%	0.0%	√
PC-03	Multi - step instructions 3	-100.0%~100.0%	0.0%	√
PC-04	Multi - step instructions 4	-100.0%~100.0%	0.0%	√
PC-05	Multi - step instructions 5	-100.0%~100.0%	0.0%	√
PC-06	Multi - step instructions 6	-100.0%~100.0%	0.0%	√
PC-07	Multi - step instructions 7	-100.0%~100.0%	0.0%	√
PC-08	Multi - step instructions 8	-100.0%~100.0%	0.0%	√
PC-09	Multi - step instructions 9	-100.0%~100.0%	0.0%	√
PC-10	Multi - step instructions 10	-100.0%~100.0%	0.0%	√
PC-11	Multi - step instructions 11	-100.0%~100.0%	0.0%	√
PC-12	Multi - step instructions 12	-100.0%~100.0%	0.0%	√
PC-13	Multi - step instructions 13	-100.0%~100.0%	0.0%	√
PC-14	Multi - step instructions 14	-100.0%~100.0%	0.0%	√
PC-15	Multi - step instructions 15	-100.0%~100.0%	0.0%	√

